

# BALLY SILVER POWER SUPPLY

## LEFTMOST CONNECTOR

## RIGHTMOST CONNECTOR

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

FUSED

1

4

GND

7

7.5  
VAC

10

+12  
VDC

13

7.5  
VAC

3

2

1

2

5

GND

8

5  
VDC

11

-12  
VDC

14

21  
VAC

6

5

4

9

8

7

12

11

10

3

GND

6

24  
VAC  
RETURN

9

5  
VDC

12

+24  
VDC

15

21  
VAC  
RETURN

15

14

13